

Tacoma Service Bulletins

A TSB is a Technical Service Bulletin. It is a fix that the factory has come up with to help the dealerships fix problems that they didn't catch during production. They are not necessarily recalls, but issues that Toyota has identified should be fixed. Typically if you identify the problem to your dealer they will fix it for free as if it were a warranty item.

Below you'll find a list of TSB's that I have been able to find.

SU002-05 REAR SUSPENSION SPRING NOISE

PD038-04 PRE-DELIVERY SERVICE (PDS) 2004-09-10

PD039-04 INITIAL CALIBRATION OF COMPASS 2004-08-10

TC006-03R INTRODUCTION OF NEW AUTOMATIC TRANSMISSION FLUID - REVISED
2004-12-03

PD008-05 POWER SYSTEM INITIALIZATION DURING PDS AND AFTER BATTERY
DISCONNECT 2005-01-27

EG045-04R ENTERING VIN DURING ECM (PCM) REPLACEMENT AND/OR DTC P0630 -
REVISED 2005-01-24

BO003-05 OVERFENDER REFINISH PROCESS 2005-03-09

BO004-05 FRONT COWL WATER LEAK REPAIR PROCEDURE 2005-03-17

EG014-05 RADIATOR CAP INSPECTION 2005-03-28

PG002-05 TIRE POSITIONING BEFORE NEW VEHICLE DELIVERY 2005-03-02

SS001-05 FAILURE TO INITIALIZE CAN INTERFACE MODULE 2005-03-11

BO004-05R FRONT COWL WATER LEAK REPAIR PROCEDURE - REVISED 2005-04-25

PD036-04 FRONT AND REAR LICENSE PLATE INSTALLATION 2004-08-30

BG045-04R ENTERING VIN DURING ECM (PCM) REPLACEMENT AND/OR DTC P0630 -
REVISED 2005-06-03

SS001-05R TOOLS - FAILURE TO INITIALIZE CAN INTERFACE MODULE - REVISED
2005-06-23

AX004-05 SKID PLATE VIBRATION 2005-07-20 NV007-05 CAB MOUNT NOISE
IMPROVEMENT 2005-06-28

PG017-02R BATTERY MAINTENANCE FOR IN-STOCK VEHICLES & PRE-DELIVERY
- REVISED 2005-06-28

AU001-05R PARASITIC DRAW FROM JBL AMPLIFIER - REVISED 2005-08-19

AU001-05 PARASITIC DRAW FROM JBL AMPLIFIER 2005-08-02

EG034-05 EXCESSIVE SULFUR DIOXIDE ODOR 2005-08-22

SS003-02R DIAGNOSTIC TESTER IMMOBILIZER TESTER FUNCTIONS - REVISED
2005-08-26

EG034-05 EXCESSIVE SULFUR DIOXIDE ODOR TSB

EG037-05R MIL ON DTC P0456 OR P0455, AND P0441 - REVISED 2005-09-16

EG037-05 MIL ON DTC P0456 OR P0455, AND P0441 2005-09-01

EG043-05 NO START IN SUB-FREEZING AMBIENT AIR TEMPERATURES - POSSIBLE
DTC P0300, P0171, P0174 2005-09-28

PG005-03R SPARE TIRE CARRIER OPERATION - REVISED 2005-09-27

BO004-07 BENT TAILGATE FIX
NV007-05 CAB MOUNT NOISE IMPROVEMENT 2005-06-28

TC004-06 CLUTCH PEDAL SQUEAK NOISE

TC-006-06 Clutch feel

ST005-01R: REPAIR MANUAL SUPPLEMENT: VEHICLE PULLING TO ONE SIDE - REVISED

PG005-03R SPARE TIRE CARRIER OPERATION - REVISED 2005-09-27

PD036-04 FRONT AND REAR LICENSE PLATE INSTALLATION 2004-08-30

BO018-07 Bent Rear Tail Gate '05 - '08 Tacoma

PG002-05 TIRE POSITIONING BEFORE NEW VEHICLE DELIVERY 2005-03-02

